


Replacing the Battery in ITI Smoke Detectors

CAUTION! Risk of explosion if battery is replaced by an incorrect type. Dispose of used batteries according to the manufacturer's instructions.

WARNING! This product contains a coin battery. If it is swallowed, it can cause severe internal burns in just 2 hours and can lead to death. Keep new and used batteries away from children. If the battery compartment does not close securely, stop using the product and keep it away from children. If you think batteries might have been swallowed or placed inside any part of the body, seek immediate medical attention.

TX-6010-01-1 Smoke Detector:

Twist counterclockwise to remove from base, open cover to replace CR123A batteries



Once you've replaced the batteries, the error on your panel should clear within one hour.

2001RFH Smoke Detector:

Twist cover to remove from base, remove and replace 2 9-Volt Alkaline batteries



Once you've replaced the batteries, the error on your panel should clear within one hour.