

Replacing the Battery in ITI Wireless Flood Detector 60-744-95R, NX-695

CAUTION! Risk of explosion if battery is replaced by an incorrect type. Dispose of used batteries according to the manufacturer's instructions.

WARNING! This product contains a coin battery. If it is swallowed, it can cause severe internal burns in just 2 hours and can lead to death. Keep new and used batteries away from children. If the battery compartment does not close securely, stop using the product and keep it away from children. If you think batteries might have been swallowed or placed inside any part of the body, seek immediate medical attention.

Press the end button to remove the cover, then remove and replace 2 AAA Alkaline batteries.



Once you've replaced the batteries, the error on your panel should clear within one hour.